

### Features

- User selectable Lux / Footcandle measurements
- Designed for one-handed operation
- Backlit 4-digit LCD display
- Max, min and data hold functions
- Low battery indicator and auto shut off
- Includes batteries

### Specifications

Measuring Ranges:	Lux: 0 to 199999 Fc: 0 to 18580
Accuracy:	0 to 9999 Lux (0 to 929 Fc): ±(4% rdg.+ 8 dgt) ≥10000 Lux (≥1000 Fc): ±(5% rdg.+ 10 dgt) ≥100000 Lux (≥9999 Fc): ±(5% rdg.+ 10 dgt) 0 to 9999 Fc: Fc = Lux/10.76 ≥10000 Fc: Fc = Lux/10.76
Resolution:	Lux: 1, 10, 100 Fc: 1, 10
Sensor Type:	Silicon photocell
Display:	4-digit LCD
Backlit Display:	Yes
Data Hold:	Yes
Min:	Yes
Max:	Yes
Overrange Indicator:	Yes
Sampling Rate:	2 times/second
Auto Shut-off:	Yes (after 5 minutes, off)
Low Battery Indicator:	Yes
Power Supply:	3 "AAA" Batteries
Product Certifications:	CE
Operating Temperature:	32 to 122°F (0 to 50°C)
Storage Temperature:	14 to 140°F (-10 to 60°C)
Operating Humidity Range:	10 to 80%
Dimensions:	6.3 x 1.9 x 1.1" (160 x 50 x 28mm)
Weight:	4.2oz (118g)

### TECHNICAL DATA



Model	Description
R1930	Light Meter, Compact Series
CA-52A	Soft Carrying Case